



## 14402 LIQUID MASK

### APPLICATION INSTRUCTIONS: SPRAY GUN AND PRESSURE:

Gun Type	Fluid Tip	Air Pressure
Siphon Feed	1.8-2.0mm	40-50 psi
Gravity Feed	1.8-2.0mm	35-45 psi
HVLP	1.8-2.0mm	10 psi

Clean gun and dry thoroughly before storing gun to avoid corrosion of internal parts.

### DIRECTIONS FOR USE:

1. Mask off surface to be painted with masking paper.
2. Apply one full wet coat of Liquid Mask on area to be protected.
3. Let dry for 20 to 30 minutes.
4. Remove any Liquid Mask overspray from surface to be painted.
5. Prepare the surface for painting as usual.
6. Apply primer, paint and/or clear and let cure as per manufacturers' recommendations.
7. Once painting and buffing process is completed and cured, simply wet vehicle with water, allow to stand for 1-2 minutes before washing.

**DRY TIME:** 20 to 30 minutes at 65-75°F (18-24°C).

**BAKING:** Liquid Mask can withstand baking temperatures of 150°F (76°C) without losing its effectiveness.

**CAUTION:** Do not use on fabric or fabric covered roofs.