



Standard Operating Procedures DeVilbiss® Clean Dirt Control Floor Coat

Description

DeVilbiss® Clean Dirt Control Floor Coat is a water-based floor coating that traps dirt and overspray circulating in the paint booth. Applied with a standard pump sprayer, the floor coat captures and transforms airborne particles into heavy dirt that it is easily swept with a broom. Regular use of this floor coating helps keep dirt and overspray out of the paint job, improving the shop's quality and profitability by reducing time spent polishing defects. It also works great in other parts of the shop.

Preparing the booth (one-time step before first using booth floor coating):

NOTE: Apply sparingly. Excessive amounts can cause floors to become slippery. Avoid spraying on booth floor grates as it could reduce filter life. The floor coat is intended for use on concrete floors. Avoid spraying the coating on tile flooring and painted floors, as it may cause the surface to become slippery.

1. Sweep the booth using a stiff push broom on the main floor, and use a smaller broom for edges, ledges, and corners. If the floor is very dirty, first spray a very light mist of booth floor coating using a two-gallon pump sprayer. This will contain the dust and overspray during the initial preparation.
3. Collect dirt and overspray in a dustpan and dispose of it in a trash container.
4. Apply approximately two quarts of floor coating in a light, even mist using a two-gallon pump sprayer such as the DeVilbiss 803492. The floor should appear damp but not shiny.

Directions for daily use

Paint booth floors

Apply sparingly. Excessive amounts can cause floors to become slippery. Avoid spraying on booth floor grates as it could reduce filter life. The floor coat is intended for use on concrete floors. Avoid spraying the coating on tile flooring and painted floors, as it may cause the surface to become slippery.

1. Sweep the booth at the start of each day and apply a uniform mist coat (approximately one quart) with a pump sprayer.
2. For best results, sweep the booth after every bake cycle using a stiff push broom.
3. Repeat the above routine daily. In high-production shops, re-apply floor coat at the mid-point of the work day.

Enjoy cleaner paint jobs and less polishing!

Supplies Needed

- Stiff push broom for booth floor (use daily)
- Small broom for sweeping edges, ledges, and corners (for booth preparation and periodically)
- Large dust pan
- 803491 DeVilbiss Clean Dirt Control Floor Coat
- 803492 DeVilbiss two-gallon pump sprayer